

Monitoring Data Record

Project Title: R-2248BB – Charlotte Outer Loop COE Action ID: 200131321
 Stream Name: UT Thomas Pond (Site 9) DWQ Number: 011231
 City, County and other Location Information: Mecklenburg County, Charlotte Outer Loop, NC 27 Exit (Mount Holly Road)
 Date Construction Completed: April 2005 Monitoring Year: (3) of 5
 Ecoregion: _____ 8 digit HUC unit 03050101
 USGS Quad Name and Coordinates: _____

Rosgen Classification: _____

Length of Project: 1148 ft. Urban or Rural: Rural Watershed Size: _____
 Monitoring DATA collected by: M. Green and J. Young Date: 3/16/10
 Applicant Information:

Name: NCDOT – Roadside Environmental Unit
 Address: 1425 Rock Quarry Rd, Raleigh, NC 27610
 Telephone Number: (919) 861-3772 Email address: mlgreen@ncdot.gov

Consultant Information:

Name: _____
 Address: _____
 Telephone Number: _____ Email address: _____

Project Status: _____

Monitoring Level required by COE and DWQ (404 permit/ 401 Cert.): Level 1

Permit States: The permittee shall perform the following components of Level I monitoring each year for the 5-year monitoring period: Reference photos; plant survival (i.e. identify specific problem areas (missing, stressed, damaged or dead plantings), estimated causes, and proposed/required remedial action); visual inspection of channel stability. Physical measurements of channel stability/morphology will not be required. The permittee shall submit the monitoring reports to the USACE, Raleigh Regulatory Field Office Project Manager, within sixty days after completing the monitoring. If less than two bankfull events occur during the first 5 years, the permittee shall continue monitoring until the second bankfull event is documented. The bankfull events must occur during separate monitoring years. In the event that the required bankfull events do not occur during the five-year monitoring period, the USACE, in consultation with the resource agencies, may determine that further monitoring is not required. It is suggested that all bankfull occurrences be monitored and reported through the required monitoring period. The permittee shall perform and submit photo documentation twice each year (summer and winter) for the 5-year monitoring period, and for any subsequently required monitoring period.

Section 1. PHOTO REFERENCE SITES

(Monitoring at all levels must complete this section)

Total number of reference photo locations at this site: 14 photos were taken from 7 photo point locations.

Dates reference photos have been taken at this site: 2/6/08, 9/3/08, 3/6/09, 9/1/09, 3/16/10

Individual from whom additional photos can be obtained (name, address, phone): _____

Other Information relative to site photo reference: A site map with photo point locations is included with this report.

If required to complete Level 3 monitoring only stop here; otherwise, complete section 2.

Section 2. PLANT SURVIVAL

Attach plan sheet indicating reference photos.

Identify specific problem areas (missing, stressed, damaged or dead plantings):

Estimated causes, and proposed/required remedial action:_____

ADDITIONAL COMMENTS: The planted vegetation is surviving and consisted of black willow, silky dogwood, green ash, tulip poplar, tag alder, swamp chestnut oak, and sycamore. Other vegetation noted included fennel, goldenrod, cattail, jewelweed, redbud, *Juncus* sp., *Scirpus* sp., sweetgum, pine, lespedeza and various grasses.

If required to complete Level 1 and Level 2 monitoring only stop here; otherwise, complete section 3.

Section 3. CHANNEL STABILITY

Visual Inspection: The entire stream project as well as each in-stream structure and bank stabilization/revetment structure must be evaluated and problems addressed.

Report on the visual inspection of channel stability. Physical measurements of channel stability/morphology will not be required. Include a discussion of any deviations from as-built and an evaluation of the significance of these deviations and whether they are indicative of a stabilizing or destabilizing situation.

UT Thomas Pond stream relocation is experiencing some instability for the Year 3 Winter evaluation. The crossvane at Sta. 217+80 -L- Photo Point #1 (Upstream) has water piping under the crossvane. A slight headcut is still located at Sta 219+00 -L- which is downstream of Photo Point #3 with no change. Another slight headcut which was noted last time at Sta. 1+00 Loop E, is still located between Photo Point #4 and #5 with no change. There were no grade control structures installed within the sections of stream where these headcuts have formed. These minor headcuts are not affecting the overall stability of the stream. There is evidence that a bankfull event has occurred since the last monitoring evaluation which has caused a divided channel to form. NCDOT will continue to monitor this stream relocation for channel stability and to see if any remedial action is warranted.

Date 3/16/10	Station Number 217+80 -L- (PP#1 Upstream)	Station Number 219+00 -L- (additional photo)	Station Number 1+00 Loop E (additional photo)	Station Number	Station Number
Structure Type	Crossvane				
Is water piping through or around structure?	Water piping under crossvane				
Head cut or down cut present?		Headcut has formed	Headcut has formed		
Bank or scour erosion present?		Station Number 219+00 -L- (additional photo)	Station Number 1+00 Loop E (additional photo)		
Other problems noted?					

UT Thomas Pond



Photo Point #1 (Upstream)



Photo Point # 1 (Downstream)



Photo Point # 2 (Upstream)



Photo Point #2 (Downstream)



Photo Point #3 (Upstream)
Year 3 Winter – March 2010



Photo Point #3 (Downstream)

UT Thomas Pond



Photo Point # 4 (Upstream)



Photo Point #4 (Downstream)



Photo Point #5 (Upstream)



Photo Point #5 (Downstream)



Photo Point #6 (Upstream)
Year 3 Winter – March 2010



Photo Point #6 (Downstream)

UT Thomas Pond



Photo Point #7 (Upstream)



Photo Point #7 (Downstream)



Headcut @ Sta. 219+00 -L-



Headcut @ Sta. 1+00 -Loop E-

Year 3 Winter – March 2010



R2248BB UT Thomas Pond
Photo Point Locations

Photo Point Locations

⊕ Photo Points



R-2248BB, UT Thomas Pond
Photo Point Locations

• Photo Points